

SAFETY DATA SHEET (SDS)

ID: C110TLS

		DATE ISSU	JED: 5/28	/2015	
SECTION 1 – PRODUCT IDENTIFICATION & COMPANY INFORMATION					
PRODUCT NAME: C11000 TIN LEAD SOLDER COPPER					
NATIONS:	TIONS:				
PRODUCT IDENTIFICATION: Copper and Copper Alloys					
MANUFACTURER'S INFORMATION:		THE ELECTRIC MATERIALS COMPANY 50 SOUTH WASHINGTON STREET NORTH EAST, PA 16428			
ONE NO.:	814-725-9621	WEBSITE:	WEBSITE: WWW.ELECMAT.COM		
RECOMMENDED USE AND RESTRICTIONS ON USE: Manufacturing & Industry for non-structural components predominantly to conduct electrical current.					
	SECTION 2 – HAZARD IDENTIFICA	ATION			
Copper and copper alloys are considered on "article" and not hazardous in solid from. However, certain processes such as cutting, milling, grinding, nand welding could result in some hazardous materials being emitted.				ling, grinding, melting	
OTHER INFORMATION: exposure limits. Dust or fumes generated by n welding or thermal cutting of the copper may			ed by machi r may prode	ning, grinding, uce airborne	
SECTION 3	3 – COMPOSITION/INFORMATION	ON INGRED	IENTS		
CHEMICAL NAME		CAS#		PERCENT WEIGHT	
Cu Copper Sn Tin Pb Lead SECTION 4 - FIRST AID ME.		7440- 7439-	31-5	99.9% 0.1% 0.1%	
Eve iniur			te medical	attention. Dust may	
be flushed from eyes immediately with large amounts of water, lifting the lower and					
Cuts or abrasions should be treated promptly with thorough cleansing of the affected area. Wash the skin using soap or mild detergent and water. Get medical attention if					
If the product or dust is swallowed, seek immediate medical attention or advice. Do not induce vomiting.			ion or advice. Do not		
If breathing has stopped, perform artificial respiration and obtain medical aid immediately. If breathing is difficult, provide fresh air and seek medical attention as soon as possible.					
	Eye injuict be flushed upper lied Cuts or a area. Wirritation of the precipitation of the pre	CT NAME: C11000 TIN LEAD SOLDER COPPERATIONS: FICATION: Copper and Copper Alloys THE ELECTRIC MATERIALS COMPERATION: 50 SOUTH WASHINGTON STREET NORTH EAST, PA 16428 FIONE NO.: 814-725-9621 RESTRICTIONS ON USE: Description of the process of th	TION 1 – PRODUCT IDENTIFICATION & COMPANY INFORMATIONS: PICATION: THE ELECTRIC MATERIALS COMPANY SO SOUTH WASHINGTON STREET NORTH EAST, PA 16428 TONE NO.: SECTION 2 – HAZARD IDENTIFICATION Copper and copper alloys are considered on "arts solid from. However, certain processes such as and welding could result in some hazardous mat exposure limits. Dust or fumes generate welding or thermal cutting of the copper contaminants. Consult Sections 3 & 8 for SECTION 3 – COMPOSITION/INFORMATION ON INGRED COMMON NAME CASSECTION 4 – FIRST AID MEASURES Eye injuries from solid particles should receive immediate be flushed from eyes immediately with large amounts of upper lids occasionally; seek medical attention. Cuts or abrasions should be treated promptly with thorwarea. Wash the skin using soap or mild detergent and we irritation develops and persists. If the product or dust is swallowed, seek immediate me induce vomiting. If breathing has stopped, perform artificial respiration a immediately. If breathing is difficult, provide fresh air a	TION 1 – PRODUCT IDENTIFICATION & COMPANY INFORMATION CT NAME: C11000 TIN LEAD SOLDER COPPER NATIONS: FICATION: Copper and Copper Alloys THE ELECTRIC MATERIALS COMPANY 50 SOUTH WASHINGTON STREET NORTH EAST, PA 16428 IONE NO.: 814-725-9621 WEBSITE: WWW.ELI ESTRICTIONS ON USE: or non-structural components predominantly to conduct electrical cuts SECTION 2 – HAZARD IDENTIFICATION Copper and copper alloys are considered on "article" and not solid from. However, certain processes such as cutting, mill and welding could result in some hazardous materials being exposure limits. Dust or fumes generated by maching welding or thermal cutting of the copper may produce contaminants. Consult Sections 3 & 8 for further in SECTION 3 – COMPOSITION/INFORMATION ON INGREDIENTS COMMON NAME CAS # Copper 7440-50-8 Tin 7440-31-5 Lead 7439-92-1 SECTION 4 – FIRST AID MEASURES Eye injuries from solid particles should receive immediate medical be flushed from eyes immediately with large amounts of water, lift upper lids occasionally; seek medical attention. Cuts or abrasions should be treated promptly with thorough cleans area. Wash the skin using soap or mild detergent and water. Get rirritation develops and persists. If the product or dust is swallowed, seek immediate medical attentinduce vomiting. If breathing has stopped, perform artificial respiration and obtain rimmediately. If breathing is difficult, provide fresh air and seek medical immediately. If breathing is difficult, provide fresh air and seek medical immediately.	

	SEC	CTION	5 – FIREFIGHTING MEASURES	
FLAMMABLE F			applicable	
EXTINGUISHING MEDIA: Not applicable; non-combustible				
	For a dust fire in a confined area, use a respirator approved for toxic d			or approved for toxic dusts
and fumes. Do not use water to extinguish fires around operations			• •	
PROTECTION OF FIREFIGHTERS: involving molten metal due to the potential for steam explosions.			•	
	SECTIO		- ACCIDENTAL RELEASE MEASURES	·
Clean-Up Procedures: Produ	ct in solid forr	n ma	y be picked up by hand or other means to b	e placed into a container.
When cleaning dust, use met	thods that min	nimize	e the dispersion of dust such as a high efficion	ency particulate air (HEPA)
vacuum, wet dust mop, or w	et clean-up. P	ut re	covered material in a suitable, covered, and	d labeled container.
	SEC		7 – HANDLING AND STORAGE	
RECOMMENDE	D STORAGE:		ntain good housekeeping to prevent exposu	
	2 31 31 31 31 32 1		nicals that may contaminate or impair the c	· · · · · · · · · · · · · · · · · · ·
			product does not require special safety pre	_
			to installation. Installation and removal of	
PROCEDURES FOR	HANDLING:	-	sure to dusts and other materials or chemi	
			llation (work) environment. Operations su	
			ing, and welding may generate dusts or fur	nes which may require
			ial handling procedures.	
			SURE CONTROLS/PERSONAL PROTECTION	C 11.
When machining, heating, or melting, use adequate local (preferably) or general exhaust ventilation to ensure that concentrations of dusts or fumes do not exceed				
ENGINEERING CONTROLS: exposure limits. Keep workplace clean and dry (unless wet machining is being us capture dust and fume). Train personnel to minimize exposure to hazards during				
	-		eplacement of product. On a regular basis,	_
			ment in which the product will be installed.	
		- quipi		
	•		1	
SUBSTANCI	•		ACGIH TLV	OSHA PEL
	•		1	OSHA PEL mg/m ³
SUBSTANCI Cu	•		ACGIH TLV mg/m ³	OSHA PEL mg/m³ 1 (dust)
	•		ACGIH TLV mg/m³ 1	OSHA PEL mg/m ³
Cu	•		ACGIH TLV mg/m³ 1 0.2	OSHA PEL mg/m³ 1 (dust) 0.2 (fume)
Cu Sn Pb	E		ACGIH TLV mg/m³ 1 0.2 2	OSHA PEL mg/m³ 1 (dust) 0.2 (fume) 2
Cu Sn Pb SUPPLEMENTAL INFORMATI	E		ACGIH TLV mg/m³ 1 0.2 2 0.15	OSHA PEL mg/m³ 1 (dust) 0.2 (fume) 2 0.15
Cu Sn Pb SUPPLEMENTAL INFORMATI Individual protection measur	ON res: Use	ical	ACGIH TLV mg/m³ 1 0.2 2 0.15 SUPPLEMENTAL INFORMATION	OSHA PEL mg/m³ 1 (dust) 0.2 (fume) 2 0.15 SUPPLEMENTAL
Cu Sn Pb SUPPLEMENTAL INFORMATI Individual protection measur appropriate gloves to protect	EON res: Use t against physi		ACGIH TLV mg/m³ 1 0.2 2 0.15 SUPPLEMENTAL INFORMATION Individual protection measures: Use an	OSHA PEL mg/m³ 1 (dust) 0.2 (fume) 2 0.15 SUPPLEMENTAL INFORMATION
Cu Sn Pb SUPPLEMENTAL INFORMATI Individual protection measur appropriate gloves to protect hazards. Always wear safety	ON res: Use t against physi glasses with s	side	ACGIH TLV mg/m³ 1 0.2 2 0.15 SUPPLEMENTAL INFORMATION Individual protection measures: Use an approved respirator, with the proper	OSHA PEL mg/m³ 1 (dust) 0.2 (fume) 2 0.15 SUPPLEMENTAL INFORMATION Individual protection: Workers should was
Cu Sn Pb SUPPLEMENTAL INFORMATI Individual protection measur appropriate gloves to protect hazards. Always wear safety shields and appropriate hear	ON res: Use t against physi glasses with s	side	ACGIH TLV mg/m³ 1 0.2 2 0.15 SUPPLEMENTAL INFORMATION Individual protection measures: Use an approved respirator, with the proper assigned protection factor, whenever airborne concentrations of hazardous components exceed exposure limits	OSHA PEL mg/m³ 1 (dust) 0.2 (fume) 2 0.15 SUPPLEMENTAL INFORMATION Individual protection: Workers should was
Cu Sn Pb SUPPLEMENTAL INFORMATI Individual protection measur appropriate gloves to protect hazards. Always wear safety shields and appropriate hear	ON res: Use t against physi glasses with s	side	ACGIH TLV mg/m³ 1 0.2 2 0.15 SUPPLEMENTAL INFORMATION Individual protection measures: Use an approved respirator, with the proper assigned protection factor, whenever airborne concentrations of hazardous	OSHA PEL mg/m³ 1 (dust) 0.2 (fume) 2 0.15 SUPPLEMENTAL INFORMATION Individual protection: Workers should was before meals and leaving
Sn Pb SUPPLEMENTAL INFORMATI Individual protection measur appropriate gloves to protect hazards. Always wear safety shields and appropriate hear when grinding or cutting.	ON res: Use t against physi glasses with s ing protection	side 1	ACGIH TLV mg/m³ 1 0.2 2 0.15 SUPPLEMENTAL INFORMATION Individual protection measures: Use an approved respirator, with the proper assigned protection factor, whenever airborne concentrations of hazardous components exceed exposure limits	OSHA PEL mg/m³ 1 (dust) 0.2 (fume) 2 0.15 SUPPLEMENTAL INFORMATION Individual protection: Workers should was before meals and leaving work.
Cu Sn Pb SUPPLEMENTAL INFORMATI Individual protection measur appropriate gloves to protect hazards. Always wear safety shields and appropriate hear when grinding or cutting. TERMS: ALL EXPOSURE LIMIT	ON res: Use t against physi glasses with s ing protection	side 1	ACGIH TLV mg/m³ 1 0.2 2 0.15 SUPPLEMENTAL INFORMATION Individual protection measures: Use an approved respirator, with the proper assigned protection factor, whenever airborne concentrations of hazardous components exceed exposure limits listed above.	OSHA PEL mg/m³ 1 (dust) 0.2 (fume) 2 0.15 SUPPLEMENTAL INFORMATION Individual protection: Workers should was before meals and leaving work.
Sn Pb SUPPLEMENTAL INFORMATI Individual protection measur appropriate gloves to protect hazards. Always wear safety shields and appropriate hear when grinding or cutting. TERMS: ALL EXPOSURE LIMIT OTHERWISE NOTED.	ON Tes: Use t against physical glasses with some protection TS REFERENCE UE/AMERICAN	side n ED HE	ACGIH TLV mg/m³ 1 0.2 2 0.15 SUPPLEMENTAL INFORMATION Individual protection measures: Use an approved respirator, with the proper assigned protection factor, whenever airborne concentrations of hazardous components exceed exposure limits listed above.	OSHA PEL mg/m³ 1 (dust) 0.2 (fume) 2 0.15 SUPPLEMENTAL INFORMATION Individual protection: Workers should was before meals and leaving work. GES (TWA) UNLESS
Sn Pb SUPPLEMENTAL INFORMATI Individual protection measur appropriate gloves to protect hazards. Always wear safety shields and appropriate hear when grinding or cutting. TERMS: ALL EXPOSURE LIMIT OTHERWISE NOTED. TLV = THRESHOLD LIMIT VAL	TS REFERENCE UE/AMERICAN JBIC METER	side n ED HE	ACGIH TLV mg/m³ 1 0.2 2 0.15 SUPPLEMENTAL INFORMATION Individual protection measures: Use an approved respirator, with the proper assigned protection factor, whenever airborne concentrations of hazardous components exceed exposure limits listed above. REIN ARE 8 HOUR TIMEWEIGHTED AVERAGE	OSHA PEL mg/m³ 1 (dust) 0.2 (fume) 2 0.15 SUPPLEMENTAL INFORMATION Individual protection: Workers should was before meals and leaving work. GES (TWA) UNLESS

ODOR/ODOR THRESHOLD:	VAPOR DENSITY:
None	Not volatile
MELTING/FREEZING POINT:	SPECIFIC GRAVITY: (relative density)
Approximately 1083°C (1980°F) for copper	$8.9 \text{ g/cm}^3 (0.32 \text{ lb./in}^3) \text{ for copper (water = 1)}$
BOILING POINT:	VAPOR PRESSURE:
2500°C (4530°F) for copper	~ 0 mm/Hg
FLASH POINT:	EVAPORATION RATE:
Not determined	Not volatile
FLAMMABILITY:	SOLUBILITY IN WATER:
Not flammable	Insoluble
UPPER & LOWER FLAMMABILITY LIMITS:	pH:
Not applicable	Not applicable
AUTO IGNITION TEMPERATURE:	VISCOSITY:
Not applicable	Not applicable
DECOMPOSITION TEMPERATURE:	PARTITION COEFFICIENT:
Not applicable	Not applicable

	SECTION 10 - STABILITY 9. DEAC	TIVITY		
SECTION 10 – STABILITY & REACTIVITY CHEMICAL STABILITY:				
Stable under normal use cond	ditions			
CONDITIONS TO AVOID:	aitions			
	F), which may soften the copper material.			
REACTIVITY:	Ty, which may sorten the copper materials	INCOMPATIBLE MATERIALS:		
Copper may react with acetylene gas to form copper acetylides, which		Dust is explosively incompatible with		
are sensitive to shock. Copper may react with strong acids to generate		sodium azide.		
explosive gas (e.g. hydrogen).				
HAZARDOUS DECOMPOSITIO		HAZARDOUS POLYMERIZATION:		
None		The melting of this product may release		
		metal oxides.		
SECTION 11 – TOXICOLOGICAL INFORMATION				
POTENTIAL HEALTH EFFECTS: Symptoms related to the physical, chemical and toxicological characteristics				
Under normal handling and use, exposure to product presents few health hazards. Dusts may cause mechanical				
irritations to eyes and skin. Ingestion may cause transient irritation of throat, stomach and gastrointestinal tract.				
Inhalation may cause coughing, nose and throat irritation, and sneezing. Higher dust exposures may cause difficulty				
breathing, congestion, and chest tightness.				
EYE CONTACT:		tion, discoloration, and damage. As a foreign		
body in the lens, copper dust may cause a dense cataract and discolor the lens.				
SKIN:	Copper can cause some irritation with possible discoloration of skin.			
	Ingestion of significant amounts of weldin	• • • • • • • • • • • • • • • • • • • •		
INGESTION:	swallowed and person is conscious, give large quantities of water to drink. Get medical			
	attention as soon as possible. Serious effects may occur if large amounts of dust are			
	swallowed.			
	Breathing metal dust may worsen symptoms of individuals with pre-existing chronic			
respiratory disease. Follow exposure guidelines for copper dust and fume. Act				
INHALATION:	INHALATION: exposure to dust or fume may cause upper respiratory tract irritation, metallic taste			
	mouth, nausea, fatigue, and/or metal fume fever. Breathing copper dust may worsen symptoms of individuals with pre-existing chronic respiratory disease.			
	Carcinogen Classification of Ingredients			
	Page 3 of 5	uiciio		

Ingredient	OSHA	NTP	IARC	Target Organ
None				

TERMS:

OSHA – Occupational Safety & Health Administration

Y = Listed as a human carcinogen

NTP - National Toxicology Program

K = Known to be a human carcinogen

R = Reasonably anticipated to be a human carcinogen (RAHC)

IARC - International Agency for Research on Cancer

1 = Carcinogenic to humans

2A = Probably carcinogenic to humans

2B = Possibly carcinogenic to humans

3 = Unclassifiable as to carcinogenicity to humans

4 = Probably not carcinogenic to humans

Other -

NL = Not listed

SECTION 12 – ECOLOGICAL INFORMATION			
ECOTOXICITY	PERSISTENCE AND DEGRADABILITY		
Not applicable	Not applicable		
BIOACCUMULATION POTENTIAL	MOBILITY IN SOIL		
Not applicable	Not applicable		

OTHER ADVERSE EFFECTS

Copper metal is relatively insoluble in water and, therefore, generally has low bioavailability. This product is not expected to present an environmental hazard. Avoid releasing dusts and fumes into the environment.

SECTION 13 – DISPOSAL CONSIDERATIONS

Recover or Recycle if possible. Dispose of according to Federal, State and Local Regulations. Dust collected from machining, welding, etc. may be classified as a hazardous waste. Consult Federal, State and Local regulations.

SECTION 14 – TRANSPORT INFORMATION			
US DEPT OF TRANSPORTATION	CANADIAN TRANSPORTATION OF		
(DOT)-HMR (Hazardous Materials Registration)	DANGEROUS GOODS (TDG)		
Not regulated	Not regulated		
UN SHIPPING NAME	UN NUMBER		
Not regulated	Not regulated		
TRANSPORT HAZARD CLASS	PACKING GROUP		
Not regulated	Not regulated		
ENVIRONMENTAL HAZARDS	LABEL(S) REQUIRED?		
None	No		
TRANSPORT IN BULK	SPECIAL SHIPPING INFORMATION		
Not applicable	Not applicable		
SECTION 15 - REGULATORY INFORMATION			

US-OSHA (HAZARD COMMUNICATION STANDARD)

References

Lead

SARA TITLE III SECTION 302 (40CFR 355), SARA TITLE III 311/312 (40 CFR 370), SARA TITLE III 313 (40 CFR 372)

Component CAS # % By Weight Copper 7440-50-8 ≥ 99.9 Tin 7440-31-5 ≥ 0.1

US-EPA (TOXIC SUBSTANCES CONTROL ACT - TSCA)

7439-92-1

All components of these products are on the TSCA inventory list or are excluded from listing.

US-EPA (SARA TITLE III)

Releases to the environment of **Copper** may be subject to reporting under Section 313 of Title III of the Superfund Amendments and Reauthorization Act of 1986 and 40 CFR Part 372.

CANADA-WHMIS (WORKPLACE HAZARDOUS MATERIALS INFORMATION SYSTEM)

≥ 0.1

This SDS has been prepared according to the hazard criteria of the Controlled Product Regulations (CPR) and the SDS contains the information required by the CPR.

CANADA DSL (DOMESTIC SUSTANCES LIST) INVENTORY STATUS

All components of these products are on the DSL Inventory.

CEPA (CANDIAN ENVIRONMENTAL PROTECTION ACT)

No components are on the Toxic Substances List.

EINECS NO. (EUROPEAN INVENTORY OF EXISTING COMMERCIAL CHEMICAL SUBSTANCES)

All components of these products are on the EINECS list.

Rohs (RESTRICTION OF CERTAIN HAZARDOUS SUBSTANCES) COMPLIANCE

Castings comply with RoHS.

CALIFORNIA PROPOSITION 65 COMPLIANCE

Copper is not on California's Proposition 65 list. (California Health & Safety Code 25248.5 et seq.)

US STATE REGULATORY INFORMATION

Some of the components listed I Section 3 (e.g., Copper) may be covered under specific state regulations.

SECTION 16 – OTHER INFORMATION

SDS PREPARED BY

The information herein is given in good faith and based on technical date The Electric Materials Company believes to be reliable. Since the conditions of use are outside our control, we assume no liability in connection with any use of this information and no warranty, expressed or implied is given. Contact the Electric Materials Company or its associates for additional information.

DATE 05/2015

NOTE:

This data and label information is offered in good faith as typical values and not as a product specification. No warranty either expressed or implied is hereby made. The recommended industrial hygiene and safe handling procedures are believed to be generally acceptable. However, each user should review the recommendations in specific context of the intended use and determine if they are appropriate.

LABEL Information: We have no current labels for C110TLS.