

SAFETY DATA SHEET (SDS)

ID: C83450

DATE ISSUED: 5/24/2015

			DATE ISSU	JED: 5/24	/2015	
SECTION 1 – PRODUCT IDENTIFICATION & COMPANY INFORMATION						
PRODUCT NAME:		E: C83450 COPPER	C83450 COPPER			
OTHER DESIGNATIONS:		5:				
PRODUCT IDENTIFICATION:		J: N/A	N/A			
MANUFACTURER'S INFORMATION:		THE ELECTRIC MATERIALS COMPANY 50 SOUTH WASHINGTON STREET NORTH EAST, PA 16428				
EMERGENCY PH	ONE NO	.: 814-725-9621	WEBSITE:	WWW.ELE	ECMAT.COM	
RECOMMENDED USE AND RESTRICTIONS ON USE: Various Castings and Terminals						
		SECTION 2 – HAZARD IDENTIFICA	ATION			
CLASSIFICA	ATION:	ndustrial Copper Castings are metallic articles that do not present hazards in their original form.				
OTHER INFORMATION: Fe eth		Fumes from hot processes may con exposure limits. Dust or fumes gen thermal cutting of the casting may processes as 8 for further informations.	tain other co erated by ma oroduce airbo	mpounds w	rith different nding, welding or	
	SECTION	3 – COMPOSITION/INFORMATION	ON INGRED	IENTS		
CHEMICAL NAME		COMMON NAME	CAS	S #	PERCENT WEIGHT	
Cu Sn Pb Zn Fe		Copper Tin Lead Zinc Iron	7440-31-5 29 7439-92-1 1.5 1314-13-2 5.5 1309-37-1 0.3		89% 2% 1.5% 5.5% 0.3%	
SECTION 4 – FIRST AID MEASURES						
EYE CONTACT:	Eye injuries from solid particles should receive immediate medical attention. Dust may be flushed from eyes immediately with large amounts of water, lifting the lower and upper lids occasionally; seek medical attention. Cuts or abrasions should be treated promptly with thorough cleansing of the affected area. Wash the skin using soap or mild detergent and water. Get medical attention if					
INGESTION:	irritation develops and persists. If the product or dust is swallowed, seek immediate medical attention or advice. Do not induce vomiting.					

	If breathing has stopped, perform artificial respiration and obtain medical aid				
INHALATION:	immediately. If breathing is difficult, provide fresh air and seek medical attention as				
	soon as possible.				
	SE	CTION	I 5 – FIREFIGHTING MEASURES		
FLAMMABLE	PROPERTIES:	Not a	applicable		
EXTINGUISH	HING MEDIA:	Not	applicable; non-combustible		
Fc			or a dust fire in a confined area, use a respirator approved for toxic dusts		
		and t	and fumes. Do not use water to extinguish fires around operations		
PROTECTION OF FI	REFIGHTERS:	invo	lving molten metal due to the potential for	steam explosions.	
	SECTIO	ON 6 -	- ACCIDENTAL RELEASE MEASURES		
			y be picked up by hand or other means to b		
			e the dispersion of dust such as a high efficie		
vacuum, wet dust mop, or w	et clean-up. F	out re	covered material in a suitable, covered, and	l labeled container.	
	SEC		I 7 – HANDLING AND STORAGE		
RECOMMENDED STORAGE: Maintain good housekeeping to prevent exposure to materials and					
			nicals that may contaminate or impair the q		
			product does not require special safety pre	_	
		prior to installation. Installation and removal of the product may cause			
PROCEDURES FOR	≀ HANDLING:	exposure to dusts and other materials or chemicals associated with the			
		installation (work) environment. Operations such as grinding, cutting,			
			burning, and welding may generate dusts or fumes which may require		
special handling procedures.					
			SURE CONTROLS/PERSONAL PROTECTION heating, or melting, use adequate local (pro	oforably) or gonoral	
		_	- · · · · · · · · · · · · · · · · · · ·	,	
	exhaust ventilation to ensure that concentrations of dusts or fumes do not exceed exposure limits. Keep workplace clean and dry (unless wet machining is being used to				
ENGINEERING CONTROLS:	capture dust and fume). Train personnel to minimize exposure to hazards during				
	installation and replacement of product. On a regular basis, verify condition and proper				
	function of equipment in which the product will be installed.				
	•	считр	ACGIH TLV	OSHA PEL	
SUBSTANC	E		mg/m³	mg/m ³	
Cu			1	1 (dust)	
			0.2	0.2 (fume)	
Sn			2	0.1	
Pb			0.15	0.15	
				= (C)	

Zn

Fe

5

5

5 (fume) 10 (dust) 5

SUPPLEMENTAL INFORMATION

Individual protection measures: Use appropriate gloves to protect against physical hazards. Always wear safety glasses with side shields and appropriate hearing protection when grinding or cutting.

SUPPLEMENTAL INFORMATION

Individual protection measures: Use an approved respirator, with the proper assigned protection factor, whenever airborne concentrations of hazardous components exceed exposure limits listed above.

SUPPLEMENTAL INFORMATION

Individual protection: Workers should was before meals and leaving work.

TERMS: ALL EXPOSURE LIMITS REFERENCED HEREIN ARE 8 HOUR TIMEWEIGHTED AVERAGES (TWA) UNLESS OTHERWISE NOTED.

TLV = THRESHOLD LIMIT VALUE/AMERICAN CONFERENCE OF GOVERNMENTAL INDUSTRIAL HYGIENISTS (ACGIH) mg/m³ = MILLIGRAMS PER CUBIC METER

PERSONAL PROTECTION: Proper hand and foot protection is recommended

CECTION O DILIVEICAL & CHEMICAL DEODERTIES					
SECTION 9 – PHYSICAL & CHEMICAL PROPERTIES					
<u> </u>	APPEARANCE/PHYSICAL STATE:				
	Metallic solid with a copper color				
ODOR/ODOR THRESHOLD:		VAPOR DENSITY:			
None		Not volatile			
MELTING/FREEZING POINT:		SPECIFIC GRAVITY: (relative density)			
Approximately 1083°C (1980°F) for copper		8.9 g/cm 3 (0.32 lb./in 3) for copper (water = 1)			
BOILING POINT:		VAPOR PRESSURE:			
2500°C (4530°F) for copper		~ 0 mm/Hg			
FLASH POINT:		EVAPORATION RATE:			
Not determined		Not volatile			
FLAMMABILITY:		SOLUBILITY IN WATER:			
Not flammable		Insoluble			
UPPER & LOWER FLAMMABIL	ITY LIMITS:	pH:			
Not applicable		Not applicable			
AUTO IGNITION TEMPERATURE:		VISCOSITY:			
Not applicable		Not applicable			
DECOMPOSITION TEMPERATURE:		PARTITION COEFFICIENT:			
Not applicable		Not applicable			

SECTION 10 – STABILITY & REACTIVITY				
CHEMICAL STABILITY:				
Stable under normal use conditions				
CONDITIONS TO AVOID:				
Temperatures > 150° C (300° F), which may soften the copper material.				
REACTIVITY:	INCOMPATIBLE MATERIALS:			
Copper may react with acetylene gas to form copper acetylides, which	Dust is explosively incompatible with			
are sensitive to shock. Copper may react with strong acids to generate sodium azide.				
explosive gas (e.g. hydrogen).				

HAZARDOUS DECOMPOSITION PRODUCTS:	HAZARDOUS POLYMERIZATION:		
None	The melting of this product may release		
	metal oxides.		

SECTION 11 – TOXICOLOGICAL INFORMATION

POTENTIAL HEALTH EFFECTS: Symptoms related to the physical, chemical and toxicological characteristics Under normal handling and use, exposure to product presents few health hazards. Dusts may cause mechanical irritations to eyes and skin. Ingestion may cause transient irritation of throat, stomach and gastrointestinal tract. Inhalation may cause coughing, nose and throat irritation, and sneezing. Higher dust exposures may cause difficulty breathing, congestion, and chest tightness.

EYE CONTACT:	If present as dust, copper may cause irritation, discoloration, and damage. As a foreign body in the lens, copper dust may cause a dense cataract and discolor the lens.		
SKIN:	Copper can cause some irritation with possible discoloration of skin.		
JKIIV.			
INGESTION:	Ingestion of significant amounts of welding electrodes is unlikely. If copper is		
	swallowed and person is conscious, give large quantities of water to drink. Get medical		
	attention as soon as possible. Serious effects may occur if large amounts of dust are		
	swallowed.		
INHALATION:	Breathing metal dust may worsen symptoms of individuals with pre-existing chronic		
	respiratory disease. Follow exposure guidelines for copper dust and fume. Acute		
	exposure to dust or fume may cause upper respiratory tract irritation, metallic taste in		
	mouth, nausea, fatigue, and/or metal fume fever. Breathing copper dust may worsen		
	symptoms of individuals with pre-existing chronic respiratory disease.		
Carcinogen Classification of Ingredients			

Carcinogen Classification of ingredients				
Ingredient	OSHA	NTP	IARC	Target Organ
None				

TERMS:

OSHA - Occupational Safety & Health Administration

Y = Listed as a human carcinogen

NTP - National Toxicology Program

K = Known to be a human carcinogen

R = Reasonably anticipated to be a human carcinogen (RAHC)

IARC – International Agency for Research on Cancer

1 = Carcinogenic to humans

2A = Probably carcinogenic to humans

2B = Possibly carcinogenic to humans

3 = Unclassifiable as to carcinogenicity to humans

4 = Probably not carcinogenic to humans

Other -

NL = Not listed

SECTION 12 – ECOLOGICAL INFORMATION			
ECOTOXICITY	PERSISTENCE AND DEGRADABILITY		
Not applicable	Not applicable		
BIOACCUMULATION POTENTIAL	MOBILITY IN SOIL		
Not applicable	Not applicable		

OTHER ADVERSE EFFECTS

Copper metal is relatively insoluble in water and, therefore, generally has low bioavailability. This product is not expected to present an environmental hazard. Avoid releasing dusts and fumes into the environment.

SECTION 13 – DISPOSAL CONSIDERATIONS

Recover or Recycle if possible. Dispose of according to Federal, State and Local Regulations. Dust collected from machining, welding, etc. may be classified as a hazardous waste. Consult Federal, State and Local regulations.

SECTION 14 – TRANSPORT INFORMATION			
US DEPT OF TRANSPORTATION	CANADIAN TRANSPORTATION OF		
(DOT)-HMR (Hazardous Materials Registration)	DANGEROUS GOODS (TDG)		
Not regulated	Not regulated		
UN SHIPPING NAME	UN NUMBER		
Not regulated	Not regulated		
TRANSPORT HAZARD CLASS	PACKING GROUP		
Not regulated	Not regulated		
ENVIRONMENTAL HAZARDS	LABEL(S) REQUIRED?		
None	No		
TRANSPORT IN BULK	SPECIAL SHIPPING INFORMATION		
Not applicable	Not applicable		

SECTION 15 - REGULATORY INFORMATION

US-OSHA (HAZARD COMMUNICATION STANDARD)

References: 29 CFR 1910.1200

A finished casting is an article as defined in the OSHA Hazard Communication Standard

29 CFR 1910.1200 (c)

29 CFR 1910.1000 Air Contaminants

Dust or fumes generated by cleaning, machining, grinding, or welding of the casting may produce airborne contaminants, such as copper and silica.

US-EPA (TOXIC SUBSTANCES CONTROL ACT - TSCA)

All components of these products are on the TSCA inventory list or are excluded from listing.

US-EPA (SARA TITLE III)

Releases to the environment of **Copper** may be subject to reporting under Section 313 of Title III of the Superfund Amendments and Reauthorization Act of 1986 and 40 CFR Part 372.

CANADA-WHMIS (WORKPLACE HAZARDOUS MATERIALS INFORMATION SYSTEM)

This SDS has been prepared according to the hazard criteria of the Controlled Product Regulations (CPR) and the SDS contains the information required by the CPR.

CANADA DSL (DOMESTIC SUSTANCES LIST) INVENTORY STATUS

All components of these products are on the DSL Inventory.

CEPA (CANDIAN ENVIRONMENTAL PROTECTION ACT)

No components are on the Toxic Substances List.

EINECS NO. (EUROPEAN INVENTORY OF EXISTING COMMERCIAL CHEMICAL SUBSTANCES)

All components of these products are on the EINECS list.

RoHS (RESTRICTION OF CERTAIN HAZARDOUS SUBSTANCES) COMPLIANCE

Castings comply with RoHS.

CALIFORNIA PROPOSITION 65 COMPLIANCE

Copper is not on California's Proposition 65 list. (California Health & Safety Code 25248.5 et seq.)

US STATE REGULATORY INFORMATION

Some of the components listed I Section 3 (e.g., Copper) may be covered under specific state regulations.

SDS PREPARED BY

The information herein is given in good faith and based on technical data The Electric Materials Company believes to be reliable. Since the conditions of use are outside our control, we assume no liability in connection with any use of this information and no warranty, expressed or implied is given. Contact the Electric Materials Company or its associates for additional information.

DATE 05/2015

NOTE:

This data and label information is offered in good faith as typical values and not as a product specification. No warranty either expressed or implied is hereby made. The recommended industrial hygiene and safe handling procedures are believed to be generally acceptable. However, each user should review the recommendations in specific context of the intended use and determine if they are appropriate.

LABEL Information: We have no current labels for C83450.